



IN UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No.: 7,892,941

Docket No: 1996-0499.01/US

Issue Date: February 22, 2011

Patentee: Pai Hung Pan

Title: TECHNIQUE FOR FORMING SHALLOW TRENCH ISOLATION STRUCTURE
WITHOUT CORNER EXPOSURE

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450
ATTN: Certificate of Correction Branch

It is requested that a Certificate of Correction be issued correcting printing errors appearing in the above-identified United States patent. Two copies of the text of the Certificate in the suggested form are enclosed.

As the error is that of the Patent Office, it is believed that no fee is due.

Issuance of the Certificate of Correction would neither expand nor contract the scope of the claims as properly allowed, and re-examination is not required.

Respectfully submitted,

Customer Number: 26809

Date: March 7, 2011

By: 
Russ Slifer
Reg. No. 39,838

CERTIFICATE UNDER 37 CFR § 1.8: The undersigned hereby certifies that this correspondence is being deposited with the United States Postal Service with sufficient postage as first class mail, in an envelope addressed to: Commissioner for Patents, P.O. Box 1450 Alexandria, VA 22313-1450, on this 7th day of March, 2011.

Shellie Bailey

/Shellie Bailey/

Name

Signature

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 7,892,941

Page (1) of 1

DATED : February 22, 2011

INVENTOR(S) : Pai Hung Pan

It is certified that errors appear in the above-identified patent and that said Letters Patent
is hereby corrected as shown below:

On the face page, in field (57), under "Abstract", in column 2, line 4, delete "Tile" and
insert -- The --, therefor.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 7,892,941

Page (1) of 1

DATED : February 22, 2011

INVENTOR(S) : Pai Hung Pan

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the face page, in field (57), under "Abstract", in column 2, line 4, delete "Tile" and insert -- The --, therefor.